

Our Cindersafe Ember Seal System is fully compliant, meeting the requirements of BOTH AS3959 & AS1530 STANDARDS

WE'RE ALL ABOUT SAFETY CINDERSAFE FIRE SEAL



WE'RE ALL ABOUT SAFETY (1)





WE'RE ALL ABOUT

SIDE/HEAD WEATHER SEALS




Centurion Garage Doors' sectional door weather seals are UV stabilsed & impact modified, thereby making them suitable for use in outdoor applications. The PVC weather seals are RoHS compliant and meet the requirements of both AS3959 & AS1530 standards which relates to their Flammability index of less than 5. By meeting these requirements, both side/head weather seals are rated to a BAL (Bushfire Attack Level) 40.






100.00



Side Seal










BAL FIRE RATING



BAL Fire Rating

BAL Low : There is insufficient risk to warrant specific construction requirements
BAL 12.5: Low risk with slight ember attack
BAL 19, 29: Moderate risk with increasing ember and heat flux levels
BAL 40: Very high risk with increasing ember and heat flux levels. Has increased likelihood of exposure to flames
BAL FZ (Flame Zone): Extreme risk with direct exposure to flames in addition to increased heat flux and ember attack

CINDERSAFE FEATURES

- Quick and easy to install without the need to drill additional holes in your walls & ceiling.
- Able to be retro fitted to existing Centurion[®] doors (gen3 track only) to allow home owners additional peace of mind and simple product upgrade.
- A more cost effective method of achieving Bush Attack Level up to BAL40.
- Can be easily removed to allow finishing trades such as painters easy access to complete, then simply clip back in place.

BRISBANE · SYDNEY · MELBOURNE · ADELAIDE · PERTH · BUNBURY

🍪 1300765537 | 1300 ROLLER | CGDOORS.COM.AU